______25X1

Copy 6 of 11

25X1

28 August 1967

MEMORANDUM FOR THE RECORD

SUBJECT: Critique for OXCART Mission Number BX6716

1. Subject mission critique was conducted in the OSA Control-Center commencing at 1500 hours, 24 August 1967.

- 2. Mission Data:
 - a. Mission Number: BX6716
 - b. Date Flown: 21 August 1967
 - c. Area of Operation: North Vietnam
 - d. Mission Success: Successful
 - e. Pilot's Name:
 - f. Aircraft Number: 131
 - g. Primary or Spare Flown: Primary
 - h. Takeoff Time Planned: 21/0235Z

Actual: 21/0343Z (Second Window)

i. Landing Time - Planned: 21/0635Z

____tal: 21/0738Z

j. Time Enroute - Planned: 4:00

Actual: 3:55

- k. Departure Base: Kadena AB
- 1. Landing Base: Kadena AB
- m. Equipment:

25X1 (1) Primar

25X1

(1) Primary:

(2) Spare: None Available

25X1

tudaka wa mmasilo
and and defined the of the agree builting of the
3 30 30 30 30 1
13.77

Approved For Release 2003/11/26:-CIA-RDP69B00041R000500060004-4

Page 2

25X1

3. Operations:

- a. Route (INS Plot vs Planned): Satisfactory.
 - (1) Comments: Excelent adherence to planned course.
 - (2) INS Terminal Error: 2.6 NM for 4+20 Nav time.
 - (3) INS Spec Error: 9.8 NM
- b. Mission Generation & Operational Support: Satisfactory.
- (1) Comments: This first operational mission flown using route options. Option decision finalized at H-8 hours.
- c. Other Comments: INS power interruption caused takeoff delay to second window timing.

4. Weather:

- a. Forecast vs Actual:
 - (1) Slightly better than briefed.
- b. Weather Scout Reporting: Satisfactory.

5. Intelligence:

- a. Target Coverage:
 - (1) 23 of 30 programmed targets covered.
 - (2) 9 first priority SSM targets of 9 covered.
 - (3) 20 of 28 first priority NVN COMOR targets covered.
 - (4) 108 SAM sites, 14 sites occupied, 1 new site.
 - (5) 13 other priority NVN COMOR targets covered.

25X1

25X1 25X1

Page	-3		
5	_		

- Quality of Take: Satisfactory. b.
- (1) Resolution: Some degradation due haze and cloud shadows. Excellent in cloud-free area--one foot at NADIR; 2 to 2.5 ft. at 20 miles from NADIR.
- (2) Camera Operation: Satisfactory. Exposure settings used satisfactory.

- Take Movement: ſ.
 - Photography: Satisfactory. (1)
 - (2)
 - Comments: Photography processed at E-K.

- Materiel:
 - Aircraft General: Satisfactory.
 - Aircraft Systems: Satisfactory.
 - (1) No. 3 inverter power interruption required update of IND system.

Approved For Release 2003/11/26: CIA-RDP69B000\(\frac{1}{4} \) 1R000500060004-4

25X1

25X1

25X1

1	Approved For Release 2003/11/26 : CIA-RDP69B00041R000500060004-4	25X
	Page 4	25X′
0EV4	7. Communications: Satisfactory.	
25X1	a. Message Traffic: Satisfactory.	
25X1	WILLIAM E. SHELTON Colonel, USAF Deputy for Operations, OSA	25X1
	OXC/O/OSA Distribution: #1 - D/SA #2 - D/O/OSA #3 - D/M/OSA #4 - D/R&D/OSA #5 - OXC/O/OSA #6 - Intel/O/OSA #7 - Wea/O/OSA #8 - Commo/O/OSA #9 - ALP/O/OSA #10 - RB/OSA #11 - CHRONO	25X1
25X1	Approved For Release 2003/11/26 : CIA-RDP69B00041R000500060004-4	